

PICKETT EQUIPMENT SERVICE BULLETIN

MAY 2022

SUBJECT: MEDIUM DUTY 60 MM BEARING

MODELS AFFECTED: TWIN MASTER COMBINE 2022, ALL OTHER TWIN MASTER COMBINES

PURPOSE:

The 60mm bearings on the threshing cylinders and the shaker table eccentric have been upgraded from a standard duty bearing to a medium duty bearing. The pilot diameter and bolt circle of the medium duty housing are compatible with the dimension on the standard duty housing.

If an upgrade to the medium duty bearing is desired and or required a shoulder spacer must be installed on the threshing cylinder to retain proper clearances.

No change is necessary to upgrade the shaker table eccentric bearings.

AFFECTED COMPONENTS:

- Threshing Cylinder 60mm Bearings
- Shaker Table Eccentric 60mm Bearings

Please reference the attached parts breakdown for part numbers of the affected components.



ITEM NO	PART NO	DESCRIPTION	QTY
1	520146	THRESHING CYLINDER, LH	1
2	520166	THRESHING CYLINDER SHROUD WELDMENT	1
3	520296	THRESHING CYLINDER MEDIUM DUTY SPACER	1
4	102302	IPTCI UCFC X12 60	1

